









Mild steel technology:

All the following solutions are reliable only if the following conditions are verified:

- Oxygen purity at least 99,95% (or 3.5).
- Lens and nozzle not damaged.
- Good quality material (certified, without oxydation, calamin or paint).
- Laser mode without distortion (air free of acid or solvent).

<u>Problem</u>	<u>Possible reasons</u>	<u>Possible solutions</u>
<p><i>Bad quality in opposite sides.</i></p> 	<ul style="list-style-type: none"> - Lens out of centering. - Nozzle hole close or not circular. - Mirror alignment not perfect. 	<ul style="list-style-type: none"> - Check lens centering. - Check nozzle conditions. - Check beam alignment.
<p><i>Wide cut at start.</i></p> 	<ul style="list-style-type: none"> - Too long or wrong lead-in. - Wrong laser line selection. - Piercing time too long. - Too much heat produced in the cut. 	<ul style="list-style-type: none"> - Check type and length of lead-in. - Check line color. - Check that piercing time is longer not more than 2 sec. of necessary. - Reduce Duty by step of 2-3%.
<p><i>Wide cut in the entire piece.</i></p> 	<ul style="list-style-type: none"> - Pressure too high. - Focal point too high. - Power too high. - Bad quality material. 	<ul style="list-style-type: none"> - Reduce pressure by step of 0.1 bar - Reduce power. - Check focal zero point.

<u>Problem</u>	<u>Possible reasons</u>	<u>Possible solutions</u>
<p><i>Material expelled on the surface, welded on the bottom.</i></p> 	<ul style="list-style-type: none"> - Power too low. - Speed too high. - Pressure too low. 	<ul style="list-style-type: none"> - Increase power. - Reduce speed. - Increase pressure.
<p><i>Light burr with angled lines on the bottom.</i></p> 	<ul style="list-style-type: none"> - Speed too high. - Power too low. - Pressure too low. 	<ul style="list-style-type: none"> - Reduce speed. - Increase duty cycle by step of 5-10%. - Increase power by step of 100 W. - Increase pressure by step of 0.1-0.2 bar

<u>Problem</u>	<u>Possible reasons</u>	<u>Possible solutions</u>
<p><i>Deep lines on cutting side.</i></p> 	<ul style="list-style-type: none"> - Too much heat in a small area. - Bad quality material. 	<ul style="list-style-type: none"> - Change cutting sequence. - Change, if possible, material quality.
<p><i>"Burned paper" effect on the bottom.</i></p> 	<ul style="list-style-type: none"> - Pressure too high. - Speed too high. 	<ul style="list-style-type: none"> - Reduce pressure by step of 0.1-0.2 bar. - Reduce speed.
<p><i>Drop burr and welded material on the bottom.</i></p> 	<ul style="list-style-type: none"> - Focal too low. - Pressure too low. 	<ul style="list-style-type: none"> - Increase the focal point by step of 0.1-0.2 mm. - Increase pressure by 0.1-0.2 bar.