




Piercing on Mild steel-O₂:

All the following solutions are reliable only if the following conditions are verified:

- Oxygen purity at least 99,95% (or 3.5).
- Lens and nozzle not damaged.
- Good quality material (certified, without oxidation, calamin or paint).
- Laser mode without distortion (air free of acid or solvent).

<u>Problem</u>	<u>Possible reasons</u>	<u>Possible solutions</u>
<p><i>The piercing explodes at the beginning.</i></p> 	<ul style="list-style-type: none"> -Duty value too high. -Pressure too high. -Focal point too deep. 	<ul style="list-style-type: none"> -Decrease Duty in the first lines by step of 1-2% -Decrease gas pressure in all lines by step of 0.1 bar. -Move up focal point by step of 0.1-0.2 mm in the first lines.
<p><i>The piercing explodes in the middle of the process.</i></p> 	<ul style="list-style-type: none"> -Duty value too high. -Pressure too high. -Focal point too deep. 	<ul style="list-style-type: none"> -Decrease Duty in all lines by step of 1-2% -Decrease gas pressure in all lines by step of 0.1 bar. -Move up focal point by step of 0.1-0.2 mm in all lines.
<p><i>The piercing explodes between the end of piercing and the beginning of cutting.</i></p> 	<ul style="list-style-type: none"> -Not enough time to pierce the material 	<ul style="list-style-type: none"> -Increase the piercing time of the last line by step of 0.5 sec. -Increase duty by step of 1-2% in all lines. -Increase pressure by step of 0.1 bar in all lines.