



# **Wiring Manual Millennium Tables**



**October 2003**

# XYZ MILLENNIUM Startup Procedure

In order to properly boot up your XYZ router table it is recommended that the following guidelines are performed on a daily basis, or whenever the table has been OFF.



- Make sure the E-stop is pulled out, before switching the table ON
- Connect the air supply to the table
- Push the Green ON button to power the table
- Sub Console display will now read "Seek X Y Origin", toggle  between Yes or No & press Enter 

(by entering the default YES the machine will travel to MRZ (Machine Reference Zero) 0,0 origin or the home position)

- Next the display will read "Warm up Spindles? Default is YES"  Toggle if need be between Yes or No & press Enter 

(by selecting the Default YES, the spindle will run at 9000 RPM for 10 minutes. This warms up the bearings inside the spindle(Recommended), and the table remains immobile during the warmup)Note:

X Y Z axes initialize  
& the table locates its  
true 0,0 origin(MRZ).



## **WARNING!!!!**

Spindle will turn on after pressing ENTER. Ensure spindle & tooling are not touching any surface. **DO NOT RUN** unless Pressure Foot or Brushfoot is installed on machine

Note: During warmup the spindle RPM reaches 9000,

## **M Series Cable Descriptions**

Cable Number	From Description	To Destination
M1	X1 Motor	J5 Millennium Connection Board
M2	Y1 Motor	J6 Millennium Connection Board
M3	Z1 Motor	J7 Millennium Connection Board
M4	X Limit Sensor	J2 Millennium Carriage Board
M5	Y Limit Sensor	J15 Millennium Connection Board
M6	Z Limit Sensor	J3 Millennium Carriage Board
M7	E Stop	J21 Millennium Connection Board
M8	Start/Stop	J22 Millennium Connection Board
M9	Carriage	J17 Millennium ConnectionBoard
M10	Inverter	P13 on AMC Board
M11	RS 485	P4 on AMC Board
M12	SubConsole	P9 on AMC Board


## **M Series Fuse Descriptions**

Fuse Number	Size / Type	Description
F1	1A Fast Blow	Contactor Protection Fuse
F2	15A Slow Blow	Inverter L1 Fuse
F3	15A Slow Blow	Inverter L2 Fuse
F4	15A Slow Blow	Optional Fuse for 3-Phase
F5	5 A Slow Blow	Control Transformer Primary L2
F6	5 A Slow Blow	Control Transformer Primary L1
F7	15 A	Optional Engraver
F8	15 A	Optional Engraver
F9	5A Fast Blow	Optional (For 18V)
F10	5A Fast Blow	Optional (For 18V)
F11	5A Fast Blow	Electronics
F12	5A Fast Blow	Electronics
F13	20A Ceramic Slow Blow	Drive Power
F14	20A Ceramic Slow Blow	Drive Power
F15	1A Fast Blow Contact Protection Fuse	Contactor Protection Fuse



(*'ak-sōz*)  
**AXYZ™**  
AUTOMATION INC.

# Millennium Wiring Diagram





(*'ak-sōz*)  
**AXYZ™**  
AUTOMATION INC.






## 208-240 VOLT 9KW Power System







# Millennium 208-220 3 ph wiring

- 3 Phase R (Black)
- 4 Phase S (White)
- 5 Phase T (Red)
- 6 GND (Green/Yellow)





# Millennium Connection Board



<b>J3 Z1</b>	<b>J2 Y1</b>	<b>J1 X1</b>
1 Not Used	1 Not Used	1 Not Used
2	2	
3	3	3
4	4	4

**J5 X1**  
1 Black  
2 Red ☐ P3 X1 Stepper Drive

**J6 Y1**  
1 Black  
2 Red ☐ P3 Y1 Stepper Drive

**J7 Z1**  
1 Black  
2 Red ☐ P3 Z1 Stepper Drive

<b>J19</b>		
6 Input 2	1 White	<input type="checkbox"/> P40 ON AMC
5 Input 1	2 Yellow	
4 Limit Sensor	3 Grey	<input type="checkbox"/> P29 ON AMC
3 Tool Sensor	4 Blue	
2 GND1	5 Black	
1 5 VDC	6 Red	
10 4 Down	7 Black	
9 4 Activate	8 Brown	
8 3 Down	9 Violet	
7 3 Activate	10 Red	
5 2 Down	11 Blue	
4 2 Activate	12 Green	
3 1 Down	13 Yellow	
2 1 Activate	14 White	
P6 2 Spindle	Not Used	
P6 4 Enable	Not Used	

**J22 START/STOP**  
1 GND BLACK  
2 12V WHITE  
3 IN RED

**J21 E-Stop**  
1 Red  
2 Black

**J12 12VDC FAN**  
Optional  
1 24 VDC  
2 12 VDC  
3 GND

**J33 12V AC**  
1 Black  
2 Red

**J26 Transformer**

1 Black  
Brown  
2 White  
Orange

**J15 Limit Sensors**  
X limit S-Mouse Opt

1 Signal  
2 12VDC  
3 GND  
Y limit  
1 Signal Black  
2 12VDC Brown  
3 GND Blue  
Z1 limit  
1 Signal Not Used  
2 12VDC Not Used  
3 GND Not Used

**J25 Spindle**  
1 Black ☐ L1  
2 Black ☐ L2 Inverter

**J35 AMC Power**  
1 White ☐ P11 AMC Board  
2 White ☐

**J32 18 VAC**  
1 Violet ☐ Not Used  
2 Brown ☐

**J34 30-50 VAC**  
1 Gray ☐ Transformer  
2 Black ☐

**J17 CARRIAGE**  
10 Y-Sen Not Used  
9 Z-Sen Black  
8 T1- Act Yellow  
7 T2-Act Orange  
6 T3-Act Violet  
5 T2-Sen Brown  
4 T3-Sen Not Used  
3 12 VDC Red  
2 GND Green  
1 Shield Green+Silver


**J24 INVERTER CONTROL**  
Not Used  
1 V+  
2 FWD  
3 V+  
4 FWD

**J31 Spindle Switch**  
1 On Not Used  
2 AUTO Black ☐ Connected Together  
3 Com Black ☐

## Fuses


F1	1 A Fast Blow
F2	15 A Slow Blow
F3	15 A Slow Blow
F4	15 A Slow Blow Opt
F5	5 A Slow Blow
F6	5 A Slow Blow
F7	15 A Opt
F8	15 A Opt
F9	5 A Opt
F10	5 A Opt
F11	5 A Fast Blow
F12	5 A Fast Blow
F13	20 A Ceramic
F14	20 A Ceramic
F15	1 A Slow Blow





(*'ak-sēz*)  
**AXYZ**<sup>TM</sup>  
 AUTOMATION INC.


# MILLENNIUM CONNECTION BOARD



(*'ak-sēz*)  
**AXYZ**<sup>TM</sup>  
 AUTOMATION INC.


FOR MILLENNIUM 3HP  
INVERTER WE DO NOT  
USE DYNAMIC BREAKING  
RESISTOR. PUT JUMPER  
WIRE BETWEEN PIN NO  
4 AND 9 INSTEED.

BREAKING RESISTOR 30 OHM  
FOR - 10HP 220V  
FOR - 5HP 220V  
BREAKING RESISTOR 100 OHM  
FOR - 10HP 440V  
FOR - 5HP 440V





## Millennium Inverter Control Wiring



L1 L2 L3 M1 M2 M3

Black Black Black White Red

To J25 on Connection Board

Spindle Cable  
GREEN  
Ground

CM MET2 MET1 VM2 VM1 REF CM PWD REV P+3 P+2 P+1 V+ V- IMOL SH NO RCM NC

USE 6 CONDUCTOR  
22 AWG CABLE




1. ADJUST J19 FROM PULL UP TO PULL DOWN LOGIC
2. WIRED CONTROL TERMINAL TO AMC AS SHOWN BELOW

INVERTER CONTROL MUST BE SWITCHED FROM PULL UP LOGIC (FACTORY DEFAULT) TO PULL DOWN LOGIC. MOVE JUMPER J19 AS SHOWN:



WRONG



CORRECT

PC 2050  
Inverter


INVERTER CONNECTOR ON  
AMC BOARD:  
INVERTER 1 - P13  
INVERTER 2 - P12






# AMC Board

## Revision G



Elec. Panel



### P11 12AC/DC POWER

### P41 X AND Y MOTOR CONTROL

- |    |              |       |
|----|--------------|-------|
| 1  | 12 VDC       | RED   |
| 2  | X1 STEP      | BLACK |
| 3  | X1 DIRECTION | BLUE  |
| 4  | X2 STEP      | BLACK |
| 5  | X2 DIRECTION | BLUE  |
| 6  | 12 VDC       | RED   |
| 7  | Y1 STEP      | BLACK |
| 8  | Y2 DIRECTION | BLUE  |
| 9  | Y2 STEP      | BLACK |
| 10 | Y2 DIRECTION | BLUE  |

### P3 Z MOTOR CONTROL

- |    |              |       |
|----|--------------|-------|
| 1  | 12 VDC       | RED   |
| 2  | Z1 STEP      | BLACK |
| 3  | Z1 DIRECTION | BLUE  |
| 4  | Z2 STEP      | BLACK |
| 5  | Z2 DIRECTION | BLUE  |
| 6  | 12 VDC       | RED   |
| 7  | Z3 STEP      | BLACK |
| 8  | Z3 DIRECTION | BLUE  |
| 9  | Z4 STEP      | BLACK |
| 10 | Z4 DIRECTION | BLUE  |

### P29 TOOL OUTPUTS

- |    |             |        |
|----|-------------|--------|
| 1  | 12 VDC      |        |
| 2  | T1 ACTIVATE | WHITE  |
| 3  | T1 DOWN     | YELLOW |
| 4  | T2 ACTIVATE | GREEN  |
| 5  | T2 DOWN     | BLUE   |
| 6  | 12 VDC      |        |
| 7  | T3 ACTIVATE | RED    |
| 8  | T3 DOWN     | PURPLE |
| 9  | T4 ACTIVATE | BROWN  |
| 10 | T4 DOWN     | BLACK  |

### P40 BASIC INPUTS

- |   |                |        |
|---|----------------|--------|
| 1 | 5 VDC          | RED    |
| 2 | GND            | BLACK  |
| 3 | TOOL BUSY      | BLUE   |
| 4 | LIMIT SENSORS  | GREY   |
| 5 | MACHINE MOTION | YELLOW |
| 6 | INPUT 2        | WHITE  |

### P6 SPINDLE OUTPUTS

- |   |                   |       |
|---|-------------------|-------|
| 1 | 12 VDC            |       |
| 2 | INVERTER 1 ON/OFF | GRAY  |
| 3 | 12 VDC            | BLUE  |
| 4 | MOTOR ENABLE      | BROWN |
| 5 | ACCELERATE        | WHITE |
| 6 | DECELERATE        |       |

### P8 LRC

- |   |          |       |
|---|----------|-------|
| 1 | 12 VDC   | GREEN |
| 2 | TRANSMIT | RED   |
| 3 | RECEIVE  | BLACK |

### P9 SUB CONSOLE

- |   |          |       |
|---|----------|-------|
| 1 | 12 VDC   | RED   |
| 2 | RECEIVE  | GREEN |
| 3 | TRANSMIT | WHITE |
| 4 | GROUND   | BLACK |

### P4 Rs485 CHANNEL B

- |   |              |       |
|---|--------------|-------|
| 1 | GROUND       |       |
| 2 | DIFF INPUT B | RED   |
| 3 | DIFF INPUT A | BLACK |
| 4 | 12 VDC       |       |

### P2 Rs485 CHANNEL D

- |   |              |                      |
|---|--------------|----------------------|
| 1 | GROUND       |                      |
| 2 | DIFF INPUT B | OPTIONAL FOR UPGRADE |
| 3 | DIFF INPUT A |                      |
| 4 | 12 VDC       |                      |

### P1 Rs485 CHANNEL C

- |   |              |  |
|---|--------------|--|
| 1 | GROUND       |  |
| 2 | DIFF INPUT B |  |
| 3 | DIFF INPUT A |  |
| 4 | 12 VDC       |  |

OPTIONAL FOR UPGRADE

### P5 ATC CONTROL

- |    |                     |        |
|----|---------------------|--------|
| 1  | GROUND              | BLACK  |
| 2  | MANUAL BUTTON INPUT | PURPLE |
| 3  | ZERO SPEED INPUT    | BLUE   |
| 4  | SENSOR 2            | ORANGE |
| 5  | SENSOR 3            | GREEN  |
| 6  | SENSOR 4            | YELLOW |
| 7  | NOT CONNECTED       |        |
| 8  | GROUND              | BLACK  |
| 9  | TOOL CLAMP SOLENOID | RED    |
| 10 | 12 VDC              |        |

### P14 ATC CARROUSEL

- |   |                |       |
|---|----------------|-------|
| 1 | GROUND         | BLACK |
| 2 | POSITION INPUT | WHITE |
| 3 | DOOR SOLENOID  | GREEN |
| 4 | 12 VDC         | RED   |

### P15 DUST COLLECTOR

- |   |                      |     |
|---|----------------------|-----|
| 1 | GROUND               |     |
| 2 | 12 VDC SOURCE OUTPUT | RED |

### P7 PUMP CONTROL (INVERTER 3)

- |   |                      |       |
|---|----------------------|-------|
| 1 | GND                  | BLACK |
| 2 | VACUUM PUMP COM      | RED   |
| 3 | VACUUM PUMP START    | GREEN |
| 4 | VACUUM PUMP STOP     | WHITE |
| 5 | VACUUM PUMP FEEDBACK | BLUE  |
| 6 | INVERTER 3 ON/OFF    |       |

### P12 INVERTER 2

- |   |            |       |
|---|------------|-------|
| 1 | GND        | BLACK |
| 2 | DECELERATE | GREEN |
| 3 | ACCELERATE | BROWN |
| 4 | 5 VDC      | WHITE |
| 5 | FEEDBACK   | RED   |
| 6 | ON/OFF     | BLUE  |

### P13 INVERTER 1

- |   |            |       |
|---|------------|-------|
| 1 | GND        | BLACK |
| 2 | DECELERATE | GREEN |
| 3 | ACCELERATE | BROWN |
| 4 | 5 VDC      | WHITE |
| 5 | FEEDBACK   | RED   |
| 6 | ON/OFF     | BLUE  |

### P10 E-STOP

- |   |             |        |
|---|-------------|--------|
| 1 | 5 VDC       |        |
| 2 | N.C. E-STOP | JUMPER |


### P17 ENCODER CONNECTOR

- |    |          |        |
|----|----------|--------|
| 1  | Output 1 |        |
| 2  | Output 2 |        |
| 3  | Output 3 |        |
| 4  | Output 4 |        |
| 5  | Input 1  | GREEN  |
| 6  | Input 2  | YELLOW |
| 7  | Input 3  |        |
| 8  | Input 4  |        |
| 9  | 5V       | ORANGE |
| 10 | GND      | BLACK  |
| 11 | 12V      |        |

For Service refer to this item as:



Part # 20810

Description: Board - AMC - 4G 4 Layers



( ' a k - s ē z )  
**XYZ**<sup>TM</sup>  
 AUTOMATION INC.

## Carriage Connection Board



### J1 Carriage

1 Shield	Shield
2 GND	Green
3 12V DC	Red
4 Tool Sensor	
5 Limit Sensor	Brown
6 Tool 4 Activate	Violet
7 Tool 3 Activate	Orange
8 Tool 2 Activate	Yellow
9 Tool 1 Activate	Black
10 Signal	

### J2 Y Limit

1 GND	Blue
2 12V	Brown
3 SIG	Black

### J3 Z1 Limit

1 GND	Blue
2 12V	Brown
3 SIG	Black

### J4 Z2 Limit

1 GND	Blue
2 12V	Brown
3 SIG	Black

### J5 Surface

1 GND	
2 12V	Black
3 SIG	Red

### J6 Laser

1 GND	
2 Vcc	

### J7 Tool

1 12V	Black
2 SIG	Red

### J8 Sensors

1 12V	
2 SIG	

### J9 T1 ACT

1 GND	
2 12V	
3 SIG	

### J10 T2 ACT

1 GND	
2 12V	
3 SIG	

### J11 T3 ACT

1 GND	
2 12V	
3 SIG	

### J12 T4 ACT

1 GND	
2 12V	
3 SIG	

For Service refer to this item as:

Part # 21314


Description: Board - Carriage, Rev. 01A





( ' a k - s ē z )  
**XYZ**<sup>TM</sup>  
 AUTOMATION INC.

## AXI Stepper Motor Drive



Elec. Panel

Control Connector

Pin	Wire Colour	Description
PIN 1	Blue	Step
PIN 2	Black	Direction
PIN 3	Red	+5V DC

Power Connector

Pin	Wire Colour	Description
PIN 1	Red	40V DC
PIN 2	Black	0. V DC
PIN 3		Ground

Motor Winding Connector (X AXIS)

Pin	Wire Colour	Description
PIN 1	Green	Phase -A
PIN 2	White	Phase +A
PIN 3	Red	Phase +B
PIN 4	Black	Phase -B

Motor Winding Connector (Y & Z)

Pin	Wire Colour	Description
PIN 1	White	Phase +A
PIN 2	Green	Phase -A
PIN 3	Red	Phase +B
PIN 4	Black	Phase -B

Micro Stepping Selector Switch

↑↑	ON	6400 microstep/rev
↑↓	ON	1600 microstep/rev
↓↑	ON	3200 microstep/rev
↓↓	ON	800 microstep/rev

DEFAULT

Model AXI Stepper Drives are a new generation of drives specifically designed for XYZ machines.

They operate at 4 amps peak power and can be programmed to 800, 1600, 3200 or 6400 steps

- AXI drives operate extremely quietly and smoothly
- The step size is much more uniform than any other drive available on the market
- AXI drives are specifically designed and programmed for the motors and loads characteristic of XYZ machines and are suitably optimized
- A much easier and reliable connection system
- No terminal screws, thereby avoiding connection problems and burning of connectors
- Two DIP switches to program the step size, greatly reducing the probability of incorrect set up
- Compact and highly efficient, greatly reducing heat in the control box

For Service refer to this item as:

Part # 21033

Description: Drive - Microstepper 8






# Gantry Transmission Y-Axis



Assembled on Gantry



## Transmission Gear Ratios

24 Tooth Pinion Effective Diameter: 1.2 inches (30.48 mm)  
Main Pulley: 60 tooth  
Minor Pulley: 18 tooth

Transmission Ratio: .88422 REV/INCH  
.3481 REV/CM


## Stepper Motor TO Stepper Drive Connection

Motor Connector		PIN	Motor Conn.	Description
	1	1	Black & Orange	Phase +A
	2	2	Yellow & Green	Phase - A
	3	3	Pink & Light Brown	Phase +B
	4	4	White & Blue	Phase - B
Cable Connector		PIN	Cable Conn.	Description
	1	1	White	Phase +A
	2	2	Green	Phase - A
	3	3	Red	Phase +B
	4	4	Black	Phase - B





## Transmission Z-Axis




VEXTA  
Step Motor  
# 20620

M8 X 25 screws

M6 Nut  
lock washer  
washer


Casting-Z  
#20253

Carriage Mounting  
Holes



POWER  
CONNECTOR


- 1 BLACK  
ORANGE
- 2 YELLOW  
GREEN
- 3 PINK  
LIGHT BROWN
- 4 WHITE  
BLUE



Motorplate

½" Pulley  
# 20610

Timing Belt Required  
120XL037  
Part # 20754



Carriage Mounting Location  
(Note: Z-Plate must be removed  
to access the holes)


### Transmission Gear Ratios

24 Tooth Pinion Effective Diameter: 1.2 inches (30.48 mm)  
Main Pulley: 60 tooth  
Minor Pulley: 18 tooth


Transmission Ratio: .88422 REV/INCH  
.3481 REV/CM

### Stepper Motor TO Stepper Drive Connection

**Motor  
Connector**



**Cable  
Connector**



PIN	Motor Conn.	Description
1	Black & Orange	Phase +A
2	Yellow & Green	Phase - A
3	Pink & Light Brown	Phase +B
4	White & Blue	Phase - B

PIN	Cable Conn.	Description
1	White	Phase +A
2	Green	Phase - A
3	Red	Phase +B
4	Black	Phase - B





## Elte Motor

Manufacturer: ELTE SRL

General Info: Elte motors are designed and built for a wide variety of applications whether it be drilling, engraving, facing etc. for many industries such as wood and light alloy processing. Features such as precision balancing, and maintenance free sealed bearings ensure fast, clean cutting, quiet operation and years of trouble free use. Also, with speeds up to 18 000RPM, the consumer is guaranteed to find the best suited model.

Models used by AXYZ Automation:


PE3-TMPE3    PE4-TMPE4

Model Specs:

### **PE3-TMPE3**


- Type TMPE3 12/2
- Voltage 230
- Hz 300
- kW 2.2
- 3 Hp
- 10 A
- RPM 18000
- weight 8 Kg

Dimensions: (in mm)





# Venture Engraver Wiring








# RS485 Converter



- RS485 converter box, with PC comm port connector.
- Data cable (various lengths can be specified)
- In-Box RS485 cable, which completes the connection between the AMC and your PC

The Toolpath software must be version 2.7 or greater in order to properly control the communication ports.



For Service refer to this item as:  
Part # 21850 Description: RS232/RS485 Converter Kit



## Pneumatic Drill Wiring

