



WRONG!!!

Shafts A and B should be positioned more apart than in this drawing, as 60 teeth gear can come in contact with 66 teeth gear. This can happen only while shifting gears, not when gears are engaged and running.





CORRECTED!!!





230.0

CORRECT DIMENSIONS

USE THIS ONE.

270.0

62.25

99.50

68.25

66.5

60


132.75

68.75

76.25

67.75

86.0



pulleys side outside 10 mm thickness

