



17	1	Pier cie �sadczy spr ynuj cy Z35	DIN 471	
16	1	�o ysko kulkowe	PN-85/M-86100 – 6307 – 35 x 80 x 21	
15	1	Nakr fka �o yskowa M70x2	PN-77/M-86478	
14	1	Podk�adka z bafu MB14A	PN-75/M-86482	
13	2	Wpust pryzmatyczny A 20x12x56	PN-70/M-85005	
12	1	Wpust pryzmatyczny A 20x12x56	PN-70/M-85005	
11	1	Pier cie �sadczy spr ynuj cy Z70	DIN 471	
10	1	Wpust pryzmatyczny A 18x11x60	PN-70/M-85005	
9	1	Pier cie �sadczy spr ynuj cy Z60	DIN 742	
8	1	�o ysko kulkowe	PN-85/M-86100 – 6306 – 30 x 72 x 19	
7	1	Zesp��		