

Tested, and it works well.

Needs a soft spring above floating disk.

Ball bearings are out of a 17mm thrust bearing.
Diameter 4.8mm

Needs an amplifier circuit to be repeatable,
don't connect to parallel port directly.

Tinning the PCB is a good idea, gold plating
would be better. Bare copper oxidizes and
breaks contact.

