



connect the pedal remote to the welder front panel socket.



Analog Regulation Type Torch Socket Interface



Digital Regulation Type Torch Socket Interface