




## Probing Results X axis (sideways, X+, all attempts)




## Probing Results X axis (sideways, X+, all attempts)




## Probing Results Z axis (down, Z-, all attempts)




## Probing Results Z axis (down, Z-, all attempts)




## Probing results X axis towards workpiece (sideways, X+)




## Probing results X axis towards workpiece (sideways, X+)



## Probing results X axis towards workpiece (sideways, X+)




## Probing results X axis towards workpiece (sideways, X+)







## Probing results X axis towards workpiece (sideways, X+)




## Probing results X axis towards workpiece (sideways, X+)




## Probing results X axis towards workpiece (sideways, X+)




## Probing results X axis towards workpiece (sideways, X+)




## Probing results Z axis towards workpiece (down, Z-)




## Probing results Z axis towards workpiece (down, Z-)



## Probing results Z axis towards workpiece (down, Z-)




## Probing results Z axis towards workpiece (down, Z-)







## Probing results Z axis towards workpiece (down, Z-)




## Probing results Z axis towards workpiece (down, Z-)




## Probing results Z axis towards workpiece (down, Z-)




## Probing results Z axis towards workpiece (down, Z-)




## Probing results Z axis towards workpiece (down, Z-)



## Probing results Z axis towards workpiece (down, Z-)



## Probing results Z axis towards workpiece (down, Z-)



## Probing results Z axis towards workpiece (down, Z-)

